

After having read the the FAA AD note draft I have noted four incorrect points (if I understand correctly this paperwork):

1 - Our address is: Z.I. de l'Arsenal - **BP** 109 (i.e. P.O. Box #) - 17303 Rochefort Cedex - France.

2 - Messier's correct address is: 45 Avenue Victor Hugo - **Bat. 227** - 93538 Aubervilliers - France.

3 - Page 3/6: The "Relevant Service Information Letter" for seats inspection is not TAAI1-25-617, but SIL TAAI1-25-059.

3 -a visual inspection of the pilot/copilot seats within the cockpit takes a few minutes only and may be performed during any airplane stops or checks.

4 - Page 5/6 & 6/6: The FAA AD note seems to require that all the actuators mentioned on table 2 of page 6/6 have to be replaced where as the Labinal units are affected only. I Am right ! Any Labinal Actuator PN 4136290005 with a sn lower than 5079 must be removed. All Labinal Actuators PN 4136290004 must be removed regardless the SN.

Hoping I don't forget anything, let me know your comments about all the points.

Best Regards.